



DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT :- The Cliff Garden (The Chatterjee Group Real Estate) Society office & Club house - The Cliff Garden, MIDC Maan Hinjewadi , phase 3, Pune 411057.

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Office Premises	Split	1.5	FTKC50UV16VF	8093081	RKC50UV16VF	8085583	3 ✓	4 ✓	6.3 ✓	L Type
2	47m Open Area	Split	2.2	FTKL71UV16M	0025173	RKL71UV16M	0025219	3 ✓	3.6 ✓	5 ✓	Jumbo
3	47m Open Area	Split	2.2	TKL71UV16M	0025176	RKL71UV16M	0025227	0	0	4 ✓	Jumbo
4	07H Open Area	Split	2.2	TKL71UV16M	0025143	RKL71UV16M	0025226	0	0	4 ✓	Jumbo
5	07H Open Area	Split	2.2	TKL71UV16M	0025170	RKL71UV16M	0025228	0	0	4 ✓	Jumbo
6											
7											
8											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
-	-	-	-	-	-	-	-	-	-	-

OTHERS Main Power Supply cable used 23.6 RMT

For Customer Details :				Vendor Details : AEON AIRCONDITIONING SOLUTIONS			
Sign :				Signature :			
Name :				Technician Name :	Tanveer Shaikh		
Date :	Stamp :			Date :	17.07.2025		

3 PinTOP - 5 NOS.
 Rubber pad - 5 NOS.
 Wrapping tape - 5 NOS.
 Drain insulation - 4 NOS.

Handwritten signature and notes:
 (Sharma,
 210715
 9765 37494)

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334167) 9322334109

Subject: **The Chatterjee Group - Society Office & Club House**

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Tanveer Shaikh		16/07/2025			
User: The Chatterjee Group				Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed	
Customer Address: Society Office & Club House, The Cliff Garden, MIDC Maan Hinjewadi						Before repair		After repair	
I Base Address: Phase 3, Pune 411057						pslg/		pslg/	
Daikin Invoice:				Date:		SP / T °C		pslg °C	
Dealer Invoice:				Date:		Current °C		Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		RKL7IUVIGM		0025226		Indoor temperature			
Indoor unit		FTKL7IUVIGM		0025143		Suction		°C	
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work	
16/07/25									
Discharge						°C		°C	
Suction						°C		°C	
Discharge						°C		°C	
Work No / Parts No		Qty		Billing Amount					
Compressor manufacturing No.		Defective Compressor		Replacement Compressor					
Installed date		Warranty		AMC		Using with		Fault location	
						Stabilizer		Phenomena code	
						Cut off		Error code	
Yes / No		Yes / No		Yes / No		Yes / No			
Service Engineer Remarks									
Daikin AC Installation done. Now AC working & cooling OK.									
Name: Tanveer Shaikh				Signature					
Customer Remarks					Customer Impression about Service				
					(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				
Name					Signature				
					a Simple Repair				
					b Part Replaced				
					c Part Repaired				
					d Gas Charging done				
					e Routine Service - Wet				
					f Routine Service - DRY				
Details of Repair Work Done									
✓									

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject: **The Chatterjee Group - Society Office & Club House**

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Tanveer Shaikh		16/07/2025			
User: The Chatterjee Group Mobile:				Operation data (Ambient temp. °C)			Fault Diagnosed		
Customer Address: Society Office & Club House				Before repair			After repair		
The Cliff Garden, MIDC Maan Hinjewadi				psig/			psig/		
I Base Address: Phase 3, Pune 411057.				HP / T			EM		
Daikin Invoice: Date:				SP / T °C			In door unit Fan Motor Defective		
Dealer Invoice: Date:				psig°C			Outdoor Fan Motor Defective		
				Current °C			Comp. taking High Current / Amp		
				Amps°C			Compressor Ground / Earth		
				Voltage			Compressor Tripping due to High Temperature		
Type				Volts			Compressor tripping due to High Pressure		
Model No				Indoor temperature			Indoor Unit MgSw Defective		
Manufacturing No.				°C			Outdoor Unit Mgsw Defective		
Outdoor unit /		RKL7HUV1GM		0025228		Suction		°C	
Indoor unit		PTKL7HUV1GM		0025170		Discharge		°C	
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work	
16/07/25								Discharge	
								Outdoor temperature	
						Suction		°C	
						Discharge		°C	
						Work No / Parts No		Qty	
						Billing Amount		Unit	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor		Gas Leakage at Indoor Unit	
								Gas Leakage at Outdoor Unit	
Installed date				Warranty		AMC		Blower broken	
								Short Cycling of Air at Indoor Unit	
								Short Cycling of Air at Outdoor Unit	
								Defect in Drain piping System	
								Gas Leakage from Flare nut	
								Error In Transmission wiring	
								Product under capacity	
								Rat bite case	
								Less cooling problem due to dirty Airfilter	
								Remote setting changed	
								Clogged Condenser	
								Other - Pl. specify	
Service Engineer Remarks				Total				Other	
Daikin Ac Installation done.								Details of Repair Work Done	
Now Ac working & cooling ok.								a Simple Repair	
Name: Tanveer Shaikh Signature								b Part Replaced	
								c Part Repaired	
Customer Remarks				Customer Impression about Service				d Gas Charging done	
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				e Routine Service - Wet	
				How is the behavior of visited engineer				f Routine Service - DRY	
				What is the level of your satisfaction					
				How is the explanation by Engineer					
Name: Signature									

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject: The Chatterjee Group - Society Office & Club House

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Tanveer Shaikh		17/07/2025			
User: <u>The Chatterjee Group</u> Mobile:				Operation data (Ambient temp. °C)				Fault Diagnosed	
Customer Address: <u>Society Office & Club House, The Cliff Garden, MIDC Maan Hinjewadi</u>				Before repair		After repair		Power	
Base Address: <u>Phase 3, Pune 411057</u>				pslg/		pslg/		In door unit PCB Defective	
Daikin Invoice:		Date:		SP / T °C		pslg °C		Out door PCB Defective	
Dealer Invoice:		Date:		Current °C		Amps °C		In door unit Fan Motor Defective	
				Voltage		Volts		Outdoor Fan Motor Defective	
Type		Model No		Manufacturing No.		Volts		Comp. taking High Current / Amp	
Outdoor unit /		RKL7HUVIGM		0025219		Indoor temperature		Compressor Ground / Earth	
Indoor unit		FTKL7HUVIGM		0025173		Suction °C		Compressor tripping due to High Temperature	
Work Date		No. of S.E.		Work hours		Progress code		Compressor tripping due to High Pressure	
17/07/25								Indoor Unit MgSw Defective	
Details of the Repair Work				Discharge °C		°C		Outdoor Unit Mgsw Defective	
				Suction °C		°C		Indoor Unit Transformer Faulty	
				Discharge °C		°C		Out door Unit Transformer Faulty	
				Work No / Parts No		Qty		Fault of swing Motor	
				Billing Amount				Defect of Drain Pump	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor		Expansion Valve Body / Motor Defective	
Installed date		Warranty		AMC		Using with		Defective Temperature Sensor of Indoor Unit	
						Stabilizer		Defective Temperature Sensor of Outdoor Unit	
						Cut off		Defective Current Sensor In Out door Unit	
Yes / No		Yes / No		Yes / No		Yes / No		Gas Leakage at Indoor Unit	
								Gas Leakage at Outdoor Unit	
Service Engineer Remarks				Fault location		Phenomena code		Blower broken	
Daikin AC Installation done. Now Ac working & cooling OK.								Short Cycling of Air at Indoor Unit	
Name		Signature						Short Cycling of Air at Outdoor Unit	
Tanveer Shaikh.								Defect in Drain piping System	
				Total				Gas Leakage from Flare nut	
								Error In Transmission wiring	
								Product under capacity	
								Rat bite case	
								Less cooling problem due to dirty Airfilter	
								Remote setting changed	
								Clogged Condenser	
								Other - Pl. specify	
Customer Remarks				Customer impression about Service				Details of Repair Work Done	
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)				a Simple Repair	
				How is the behavior of visited engineer				b Part Replaced	
				What is the level of your satisfaction				c Part Repaired	
				How is the explanation by Engineer				d Gas Charging done	
								e Routine Service - Wet	
								f Routine Service - DRY	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (932234107) 932234109

Subject: **The Chatterjee Group - Society Office & Club House**

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Tanveer Shaikh		17/07/2025			
User: The Chatterjee Group Mobile:				Operation data (Ambient temp. °C)			Fault Diagnosed		
Customer Address: Society Office & Club House				Before repair			After repair		
The Cliff Garden, MIDC Maan Hinjewadi,				HF/T	psig/	psig/			
I Base Address: Phase 3, Pune 411057									
Daikin Invoice:		Date:		SP/T °C	psig °C	psig °C			
Dealer Invoice:		Date:		Current °C	Amps °C	Amps °C			
Type	Model No		Manufacturing No.		Voltage	Volts	Volts		
Outdoor unit /	RKL7HUV16M		0025227		Indoor temperature				
Indoor unit	FTKL7HUV16M		0025176		Suction	°C	°C		
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work			Discharge	°C	°C
17/							Outdoor temperature		
07/							Suction	°C	°C
25							Discharge	°C	°C
				Work No / Parts No		Qty	Billing Amount		Unit
Compressor manufacturing No.		Defective Compressor		Replacement Compressor					
Installed date	Warranty	AMC	Using with		Fault location	Phenomena code	Error code		
	Yes / No	Yes / No	Yes / No	Yes / No					
Service Engineer Remarks									
Daikin AC Installation done. Now AC working & cooling ok.									
Name: Tanveer Shaikh.				Signature					
Customer Remarks				Customer Impression about Service					
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)					
Name:				How is the behavior of visited engineer				a Simple Repair	
				What is the level of your satisfaction				b Part Replaced	
				How is the explanation by Engineer				c Part Repaired	
								d Gas Charging done	
								e Routine Service - Wet	
								f Routine Service - DRY	
								Details of Repair Work Done	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject: **The Chatterjee Group - Society Office & Club House.**

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Tanveer Shaikh		17/07/2025			
User: The Chatterjee Group Mobile:				Operation data (Ambient temp. °C)			Fault Diagnosed		
Customer Address: Society Office & Club House,				Before repair			After repair		
The Cliff Garden, MIDC Maan Hingewadi,				pslg/			pslg/		
I Base Address: Phase 3, Pune 411057.				HP / T			EM		
Daikin Invoice: Date:				SP / T °C			In door unit Fan Motor Defective		
Dealer Invoice: Date:				pslg °C			Outdoor Fan Motor Defective		
				Current °C			Comp. taking High Current / Amp		
				Amps °C			Compressor Ground / Earth		
				Amps °C			Compressor Tripping due to High Temperature		
				Voltage			Compressor tripping due to High Pressure		
				Volts			Indoor Unit MgsW Defective		
				Volts			Outdoor Unit MgsW Defective		
Type Model No Manufacturing No.				Indoor temperature			Indoor Unit Transformer Faulty		
Outdoor unit / R1KCSOUV18VF 8085583				Suction °C °C			Cut door Unit Transformer Faulty		
Indoor unit FTKCSOUV18VF 8093081				Discharge °C °C			Fault of swing Motor		
Work Date No. of S.E. Work hours Progress code				Outdoor temperature			Defect of Drain Pump		
17/07/25				Suction °C °C			Expansion Valve Body / Motor Defective		
Details of the Repair Work				Discharge °C °C			Defective Temperature Sensor of Indoor Unit		
				Suction °C °C			Defective Temperature Sensor of Outdoor Unit		
				Discharge °C °C			Defective Current Sensor In Outdoor Unit		
				Work No / Parts No		Qty	Billing Amount		Unit
									Gas Leakage at Indoor Unit
									Gas Leakage at Outdoor Unit
Compressor manufacturing No. Defective Compressor Replacement Compressor									Blower broken
Installed date Warranty AMC Using with Stabilizer Cut off Fault location Phenomena code Error code									Short Cycling of Air at Indoor Unit
Yes / No Yes / No Yes / No Yes / No									Short Cycling of Air at Outdoor Unit
									Defect in Drain piping System
									Gas Leakage from Flare nut
									Error In Transmission wiring
									Product under capacity
									Flat bite case
									Less cooling problem due to dirty Airtfilter
									Remote setting changed
									Clogged Condenser
									Other - Pl. specify
Service Engineer Remarks				Total					Details of Repair Work Done
Daikin AC Installation done. Now AC working & cooling ok.									a Simple Repair
Name: Tanveer Shaikh Signature									b Part Replaced
									c Part Repaired
Customer Remarks				Customer Impression about Service					d Gas Charging done
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)					e Routine Service - Wet
				How is the behavior of visited engineer					f Routine Service - DRY
				What is the level of your satisfaction					
				How is the explanation by Engineer					
Name: Signature									