



# AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,  
Dr. Ambedkar Rd. Thane 400 601. Maharashtra

Tel. : 022 - 25370101 / 7900097007

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project :

Blue Dart. (ABC compound. Asha Nagar. Mulund (west))

## Additional Measurement Sheet

| Sr. No | Location    | AC Type | Tonnage | Indoor Unit Details |         | Outdoor Unit Details |         | Copper<br>In Rmt | Cable In<br>Rmt | Drain<br>In Rmt | ODU Stand |
|--------|-------------|---------|---------|---------------------|---------|----------------------|---------|------------------|-----------------|-----------------|-----------|
|        |             |         |         | Model No.           | Sr. No. | Model No.            | Sr. No. |                  |                 |                 |           |
| 1      | Sales Dept  | Split   | 1.8tr   | FTKM60              | 0038    | RKM60U               | 0040    | 21.34            | 23.0            | —               | 1 (Jumbo) |
| 2      | Sales Dept  | Split   | 1.8tr   | UV16U               | 065     | UV16U                | 481     |                  |                 |                 |           |
| 3      | Sales Dept. | Split   | 1.8tr   | FTKM60              | 0038    | RKM60U               | 0040    | 24.39            | 26.0            | —               | 1 (Jumbo) |
| 4      |             |         |         | UV16U               | 058     | UV16U                | 681     |                  |                 |                 |           |
| 5      |             |         |         |                     |         |                      |         |                  |                 |                 |           |
| 6      |             |         |         |                     |         |                      |         |                  |                 |                 |           |
| 7      |             |         |         |                     |         |                      |         |                  |                 |                 |           |
| 8      |             |         |         |                     |         |                      |         |                  |                 |                 |           |

## Extra Activity Carried Out

| Civil Work | Stabilizer |      |      | Timer | Casing<br>Capping | Cable Tray | Gas<br>Charging | Dismantling |          | Re-installation |
|------------|------------|------|------|-------|-------------------|------------|-----------------|-------------|----------|-----------------|
|            | 3KVA       | 4KVA | 5KVA |       |                   |            |                 | Hi Wall     | Cassette |                 |
|            |            |      |      |       |                   |            |                 | 2           |          |                 |
| Others     |            |      |      |       |                   |            |                 |             |          |                 |

For

Sign

Name

Date

Vendor Details

Signature

Technician  
Name

Date

*Imran*

Imran Alam.

24/02/24


Stamp

*24/12/24*

DAIKIN

# DAIKIN AIRCONDITIONING INDIA PVT. LTD.

## Service Completion Certificate



### AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,  
R.W. Swaant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.  
Mob.: 9322334107 / 9322334109

Subject: Installation

|                                                         |             |              |               |                            |  |                                   |  |                    |  |
|---------------------------------------------------------|-------------|--------------|---------------|----------------------------|--|-----------------------------------|--|--------------------|--|
| Registration No.                                        |             | Request Date |               | Service Engineer           |  | Scheduled Date/Time               |  | Service Order      |  |
|                                                         |             |              |               | Imran Alam                 |  |                                   |  |                    |  |
| User: <u>Blue Dart</u>                                  |             |              |               | Mobile:                    |  | Operation data (Ambient temp. °C) |  | Fault Diagnosed    |  |
| Customer Address: <u>ABC Compound Asha Nagar</u>        |             |              |               |                            |  | Before repair                     |  | After repair       |  |
| Base Address: <u>Mulund (west)</u>                      |             |              |               |                            |  | HP / T                            |  | pslg/              |  |
| Daikin Invoice:                                         |             |              |               | Date:                      |  | SP / T °C                         |  | pslg/°C            |  |
| Dealer Invoice:                                         |             |              |               | Date:                      |  | Current °C                        |  | Amps°C             |  |
| Type                                                    |             | Model No     |               | Manufacturing No.          |  | Voltage                           |  | Volts              |  |
| Outdoor unit /                                          |             | RKM60UV16U   |               | 0040681                    |  | Indoor temperature                |  |                    |  |
| Indoor unit                                             |             | FTKM60UV16U  |               | 0038058                    |  | Suction                           |  | °C                 |  |
| Work Date                                               | No. of S.E. | Work hours   | Progress code | Details of the Repair Work |  | Discharge                         |  | °C                 |  |
| 24/12/24                                                |             |              |               | Installation Done.         |  | Suction                           |  | °C                 |  |
| 24                                                      |             |              |               |                            |  | Discharge                         |  | °C                 |  |
| Compressor manufacturing No.                            |             |              |               | Defective Compressor       |  | Replacement Compressor            |  | Work No / Parts No |  |
|                                                         |             |              |               |                            |  |                                   |  | Qty                |  |
| Installed date                                          |             |              |               | Warranty                   |  | AMC                               |  | Billing Amount     |  |
| 24/12/24                                                |             |              |               | Yes / No                   |  | Yes / No                          |  | Using with         |  |
|                                                         |             |              |               |                            |  |                                   |  | Stabilizer         |  |
|                                                         |             |              |               |                            |  |                                   |  | Cut off            |  |
|                                                         |             |              |               |                            |  |                                   |  | Fault location     |  |
|                                                         |             |              |               |                            |  |                                   |  | Phenomena code     |  |
|                                                         |             |              |               |                            |  |                                   |  | Error code         |  |
| Service Engineer Remarks                                |             |              |               |                            |  |                                   |  |                    |  |
| Name                                                    |             |              |               |                            |  |                                   |  |                    |  |
| Signature                                               |             |              |               |                            |  |                                   |  |                    |  |
| Customer Remarks                                        |             |              |               |                            |  |                                   |  |                    |  |
| Name                                                    |             |              |               |                            |  |                                   |  |                    |  |
| Signature                                               |             |              |               |                            |  |                                   |  |                    |  |
| Customer Impression about Service                       |             |              |               |                            |  |                                   |  |                    |  |
| (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent) |             |              |               |                            |  |                                   |  |                    |  |
| How is the behavior of visited engineer                 |             |              |               |                            |  |                                   |  |                    |  |
| What is the level of your satisfaction                  |             |              |               |                            |  |                                   |  |                    |  |
| How is the explanation by Engineer                      |             |              |               |                            |  |                                   |  |                    |  |
| Installation 1 Nos.                                     |             |              |               |                            |  |                                   |  |                    |  |
| Copper Pipe 24.39 Mtr                                   |             |              |               |                            |  |                                   |  |                    |  |
| 4C power cable 26.0 Mtr                                 |             |              |               |                            |  |                                   |  |                    |  |
| Jumbo stand 1 NOS.                                      |             |              |               |                            |  |                                   |  |                    |  |
| Total                                                   |             |              |               |                            |  |                                   |  |                    |  |
| Details of Repair Work Done                             |             |              |               |                            |  |                                   |  |                    |  |
| a Simple Repair                                         |             |              |               |                            |  |                                   |  |                    |  |
| b Part Replaced                                         |             |              |               |                            |  |                                   |  |                    |  |
| c Part Repaired                                         |             |              |               |                            |  |                                   |  |                    |  |
| d Gas Charging done                                     |             |              |               |                            |  |                                   |  |                    |  |
| e Routine Service - Wet                                 |             |              |               |                            |  |                                   |  |                    |  |
| f Routine Service - DRY                                 |             |              |               |                            |  |                                   |  |                    |  |

DAIKIN

# DAIKIN AIRCONDITIONING INDIA PVT. LTD.

## Service Completion Certificate



**AEON AIRCONDITIONING SOLUTIONS**  
Office No. 108 & 109, Devashree Garden, Commercial Complex,  
R.W. Swaant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.  
Mob.: 9322334107 / 9322334109

1175

Subject: *Disemintal (2 Nos Ac)*

|                                                                  |             |                  |               |                                  |  |                        |                |               |  |
|------------------------------------------------------------------|-------------|------------------|---------------|----------------------------------|--|------------------------|----------------|---------------|--|
| Registration No.                                                 |             | Request Date     |               | Service Engineer                 |  | Scheduled Date/Time    |                | Service Order |  |
|                                                                  |             |                  |               | <i>Imran Alam</i>                |  |                        |                |               |  |
| User: <i>Blue Dart</i>                                           |             |                  |               | Mobile:                          |  | Fault Diagnosed        |                |               |  |
| Customer Address: <i>ABC Compound, Asha Nagar, Mulund (West)</i> |             |                  |               |                                  |  | ✓                      |                |               |  |
| I Base Address:                                                  |             |                  |               |                                  |  |                        |                |               |  |
| Daikin Invoice:                                                  |             |                  |               | Date:                            |  |                        |                |               |  |
| Dealer Invoice:                                                  |             |                  |               | Date:                            |  |                        |                |               |  |
| Type                                                             |             | Model No         |               | Manufacturing No.                |  |                        |                |               |  |
| Outdoor unit /                                                   |             | <i>Panasonic</i> |               | <i>Panasonic</i>                 |  |                        |                |               |  |
| Indoor unit                                                      |             |                  |               |                                  |  |                        |                |               |  |
| Work Date                                                        | No. of S.E. | Work hours       | Progress code | Details of the Repair Work       |  |                        |                |               |  |
| <i>24/12/19</i>                                                  |             |                  |               | <i>2 Nos Ac Disemintal Done.</i> |  |                        |                |               |  |
| Compressor manufacturing No.                                     |             |                  |               | Defective Compressor             |  | Replacement Compressor |                |               |  |
| Installed date                                                   |             | Warranty         | AMC           | Using with                       |  | Fault location         | Phenomena code | Error code    |  |
|                                                                  |             | Yes / No         | Yes / No      | Stabilizer Cut off               |  |                        |                |               |  |
| Service Engineer Remarks                                         |             |                  |               |                                  |  |                        |                |               |  |
| Name                                                             |             |                  |               |                                  |  |                        |                |               |  |
| Signature                                                        |             |                  |               |                                  |  |                        |                |               |  |
| Customer Remarks                                                 |             |                  |               |                                  |  |                        |                |               |  |
| Name                                                             |             |                  |               |                                  |  |                        |                |               |  |
| Signature                                                        |             |                  |               |                                  |  |                        |                |               |  |
| Operation data (Ambient temp. °C)                                |             |                  |               |                                  |  |                        |                |               |  |
|                                                                  |             | Before repair    |               | After repair                     |  |                        |                |               |  |
| HP / T                                                           |             | pslg/            |               | pslg/                            |  |                        |                |               |  |
| SP / T °C                                                        |             | pslg/°C          |               | pslg/°C                          |  |                        |                |               |  |
| Current °C                                                       |             | Amps°C           |               | Amps°C                           |  |                        |                |               |  |
| Voltage                                                          |             | Volts            |               | Volts                            |  |                        |                |               |  |
| Indoor temperature                                               |             |                  |               |                                  |  |                        |                |               |  |
| Suction                                                          |             | °C               |               | °C                               |  |                        |                |               |  |
| Outdoor temperature                                              |             |                  |               |                                  |  |                        |                |               |  |
| Suction                                                          |             | °C               |               | °C                               |  |                        |                |               |  |
| Discharge                                                        |             | °C               |               | °C                               |  |                        |                |               |  |
| Work No / Parts No                                               |             | Qty              |               | Billing Amount                   |  |                        |                |               |  |
| <i>2 Nos Ac Disemintal</i>                                       |             | <i>2 Nos</i>     |               | <i>1</i>                         |  |                        |                |               |  |
| Total                                                            |             |                  |               |                                  |  |                        |                |               |  |
| Unit                                                             |             |                  |               |                                  |  |                        |                |               |  |
| Installation                                                     |             |                  |               |                                  |  |                        |                |               |  |
| Other                                                            |             |                  |               |                                  |  |                        |                |               |  |
| Details of Repair Work Done                                      |             |                  |               |                                  |  |                        |                |               |  |
| Customer Impression about Service                                |             |                  |               |                                  |  |                        |                |               |  |
| (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)          |             |                  |               |                                  |  |                        |                |               |  |
| How is the behavior of visted engineer                           |             |                  |               |                                  |  |                        |                |               |  |
| What is the level of your satisfaction                           |             |                  |               |                                  |  |                        |                |               |  |
| How is the explanation by Engineer                               |             |                  |               |                                  |  |                        |                |               |  |

DAIKIN

# DAIKIN AIRCONDITIONING INDIA PVT. LTD.

## Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Colaba, Mumbai - 400 001.  
R.W. Swant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.  
Mob.: 9322334107 / 9322334109

Dec 24, 2024 11:58

03A01A

Subject: Installation

|                                                         |             |              |                    |                            |                |                                             |  |                 |  |
|---------------------------------------------------------|-------------|--------------|--------------------|----------------------------|----------------|---------------------------------------------|--|-----------------|--|
| Registration No.                                        |             | Request Date |                    | Service Engineer           |                | Scheduled Date/Time                         |  | Service Order   |  |
|                                                         |             |              |                    | Imran Alam.                |                |                                             |  |                 |  |
| User: <u>Blue Dart.</u>                                 |             |              |                    | Mobile:                    |                | Operation data (Ambient temp. °C)           |  |                 |  |
| Customer Address: <u>ABC Compound Asha.</u>             |             |              |                    |                            |                | Before repair                               |  | After repair    |  |
| Base Address: <u>Nagar, Mulund (west).</u>              |             |              |                    |                            |                | HP / T                                      |  | pslg/ pslg/     |  |
| Daikin Invoice:                                         |             |              |                    | Date:                      |                | SP / T °C                                   |  | pslg °C pslg °C |  |
| Dealer Invoice:                                         |             |              |                    | Date:                      |                | Current °C                                  |  | Amps °C Amps °C |  |
| Type                                                    |             | Model No     |                    | Manufacturing No.          |                | Voltage                                     |  | Volts Volts     |  |
| Outdoor unit /                                          |             | RKM60UV16U   |                    | 0040481                    |                | Indoor temperature                          |  |                 |  |
| Indoor unit                                             |             | FTKM60UV16U  |                    | 0038065                    |                | Suction                                     |  | °C °C           |  |
| Work Date                                               | No. of S.E. | Work hours   | Progress code      | Details of the Repair Work |                |                                             |  |                 |  |
| 24/12/24                                                |             |              |                    | Installation Done.         |                |                                             |  |                 |  |
| Compressor manufacturing No.                            |             |              |                    | Defective Compressor       |                | Replacement Compressor                      |  |                 |  |
| Installed date                                          | Warranty    | AMC          | Using with         | Fault location             | Phenomena code | Error code                                  |  |                 |  |
|                                                         | Yes / No    | Yes / No     | Stabilizer Cut off |                            |                |                                             |  |                 |  |
| Service Engineer Remarks                                |             |              |                    |                            |                |                                             |  |                 |  |
| Name: <u>Imran</u> Signature                            |             |              |                    |                            |                |                                             |  |                 |  |
| Customer Remarks                                        |             |              |                    |                            |                |                                             |  |                 |  |
| Name: <u>24/12/24</u> Signature                         |             |              |                    |                            |                |                                             |  |                 |  |
| Customer Impression about Service                       |             |              |                    |                            |                | Installation                                |  |                 |  |
| (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent) |             |              |                    |                            |                | Copper pipe 21.34 Mtr.                      |  |                 |  |
| How is the behavior of visited engineer                 |             |              |                    |                            |                | AC power cable 23.0 Mtr.                    |  |                 |  |
| What is the level of your satisfaction                  |             |              |                    |                            |                | Jumbo stand 1 Nos.                          |  |                 |  |
| How is the explanation by Engineer                      |             |              |                    |                            |                | Total                                       |  |                 |  |
|                                                         |             |              |                    |                            |                | Unit                                        |  |                 |  |
|                                                         |             |              |                    |                            |                | Gas Leakage at Indoor Unit                  |  |                 |  |
|                                                         |             |              |                    |                            |                | Gas Leakage at Outdoor Unit                 |  |                 |  |
|                                                         |             |              |                    |                            |                | Blower broken                               |  |                 |  |
|                                                         |             |              |                    |                            |                | Short Cycling of Air at Indoor Unit         |  |                 |  |
|                                                         |             |              |                    |                            |                | Short Cycling of Air at Outdoor Unit        |  |                 |  |
|                                                         |             |              |                    |                            |                | Defect in Drain piping System               |  |                 |  |
|                                                         |             |              |                    |                            |                | Gas Leakage from Flare nut                  |  |                 |  |
|                                                         |             |              |                    |                            |                | Error in Transmission wiring                |  |                 |  |
|                                                         |             |              |                    |                            |                | Product under capacity                      |  |                 |  |
|                                                         |             |              |                    |                            |                | Rat bite case                               |  |                 |  |
|                                                         |             |              |                    |                            |                | Less cooling problem due to dirty Airfilter |  |                 |  |
|                                                         |             |              |                    |                            |                | Remote setting changed                      |  |                 |  |
|                                                         |             |              |                    |                            |                | Clogged Condenser                           |  |                 |  |
|                                                         |             |              |                    |                            |                | Other - PL specify                          |  |                 |  |
|                                                         |             |              |                    |                            |                | Details of Repair Work Done                 |  |                 |  |
|                                                         |             |              |                    |                            |                | a Simple Repair                             |  |                 |  |
|                                                         |             |              |                    |                            |                | b Part Replaced                             |  |                 |  |
|                                                         |             |              |                    |                            |                | c Part Repaired                             |  |                 |  |
|                                                         |             |              |                    |                            |                | d Gas Charging done                         |  |                 |  |
|                                                         |             |              |                    |                            |                | e Routine Service - Wet                     |  |                 |  |
|                                                         |             |              |                    |                            |                | f Routine Service - DRY                     |  |                 |  |