



AEON AIRCONDITIONING SOLUTIONS
Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra
Tel. : 022 - 25370101 / 7900097007
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

065

Project : Mi store - Bail Bazaar, Kalyan

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Work Area	Cassette	4.0TR	R21FQ1404V16	0003529	R21FQ1404V16	0002868	23ft	60ft	8ft	
2											
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
									02	4.0TR Cassette - 01

Others Nitrogen flushing Testing done.

For <u>Mi store</u>	Vendor Details <u>Aeon Airconditing Solutions</u>	
Sign <u>[Signature]</u>	Signature	
Name <u>Mi store Kalyan</u>	Technician Name <u>Shoaib</u>	
Date <u>22/11/25</u>	Date <u>22/11/25</u>	

Stamp



DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Shop No. 6 & 7, Aeon House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (9322334107) 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: Mistore				Mobile :		Operation data (Ambient temp. °C)		Fault Diagnosed	
Customer Address: Bail Bazaar, Kalyan								☒	
I Base Address :									
Daikin Invoice :				Date :		HP/T		Before repair	
Dealer Invoice :				Date :		SP / T °C		After repair	
Type				Model No		Current °C		Amps °C	
Outdoor unit /				RZVF140A/16 0002868		Voltage		Volts	
Indoor unit				ECV140A/16 0003529		Indoor temperature			
Work Date				No. of S.E.		Work hours		Progress code	
28				11		25			
Details of the Repair Work				4.0TR Cassette unit		Discharge		°C	
				Re-installed working		Suction		°C	
				Cooling fine.		Discharge		°C	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor			
Installed date				Warranty		AMC		Using with	
				Yes / No		Yes / No		Stabilizer	
								Cut off	
								Fault location	
								Phenomena code	
								Error code	
Service Engineer Remarks				Name Shoaib		Signature			
Customer Remarks				Visible watermark on a ceiling		Signature			
Customer Impression about Service				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		a		Simple Repair	
						b		Part Replaced	
						c		Part Repaired	
						d		Gas Charging done	
						e		Routine Service - Wet	
						f		Routine Service - DRY	
								Details of Repair Work Done	
								☒	

Daikin Customer Care : Missed Call or SMS >DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com



Scanned with OKEN Scanner