



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,

Dr. Ambedkar Rd. Thane 400 601. Maharashtra

Tel. : 022 - 25370101 / 7900097007

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

403

Project : Bajaj housing finance (marol)

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	garwar room	5 split						3.9	5.4	-	-
2	office area	split	1.5	FTKMSOUV16VA	8196827	RKMSOUV16VA	8233960	8.2	9.4	-	-
3											
4											
5											
6											
7											
8											
Extra Activity Carried Out											
Civil Work		Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
		3KVA	4KVA	5KVA					Hi Wall	Cassette	
									2		Dismantle of odu unit - INOS Re-installation of odu unit - INOS
Others						Vendor Details					
For						Signature					
Sign						Technician Name					
Name						Date					
Date											

DAIKIN
404
DAIKIN AIRCONDITIONING INDIA PVT. LTD.
 Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS

 Office No. 108 & 109, Devashree Garden, Commercial Complex,
 R.W. Swam Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
 Mob.: 9322334107 / 9322334109

 Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Firoz					
User: <u>Bajaj housing Finance Ltd.</u> Mobile:				Operation data (Ambient temp. °C)			Fault Diagnosed		
Customer Address: <u>B 101 1st floor Polaris, off marol</u>									
I Base Address: <u>maroshi road, marol, Andheri east</u>									
Daikin Invoice:				Date:		SP / T °C		PSIG °C	
Dealer Invoice:				Date:		Current °C		Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		<u>R135 W16W3</u>		<u>S244</u>		Indoor temperature			
Indoor unit		<u>FTKM S0W16WA</u>		<u>8198121</u>		Suction		°C	
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work	
<u>13</u>								Installation Done. Now	
<u>07</u>								A.C working cooling fine.	
<u>25</u>									
Compressor manufacturing No.				Defective Compressor		Replacement Compressor			
Installed date		Warranty		AMC		Using with		Fault location	
						Stabilizer Cut off		Phenomena code	
		Yes / No		Yes / No		Yes / No		Error code	
Service Engineer Remarks									
Firoz + Abid									
Name									
Customer Remarks									
Name <u>Abhijeet S. Mohite</u>									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - Dry									
Details of Repair Work Done									
Power Failure									
Phase Reverse									
In door unit PCB Defective									
Out door PCB Defective									
In door unit Fan Motor Defective									
Outdoor Fan Motor Defective									
Comp. taking High Current / Amp									
Compressor Ground / Earth									
Compressor Tripping due to High Temperature									
Compressor tripping due to High Pressure									
Indoor Unit MgsW Defective									
Outdoor Unit MgsW Defective									
Indoor Unit Transformer Faulty									
Out door Unit Transformer Faulty									
Fault of swing Motor									
Defect of Drain Pump									
Expansion Valve Body / Motor Defective									
Defective Temperature Sensor of Indoor Unit									
Defective Temperature Sensor of Outdoor Unit									
Defective Current Sensor In Out door Unit									
Gas Leakage at Indoor Unit									
Gas Leakage at Outdoor Unit									
Blower broken									
Short Cycling of Air at Indoor Unit									
Short Cycling of Air at Outdoor Unit									
Defect in Drain piping System									
Gas Leakage from Flare nut									
Error in Transmission wiring									
Product under capacity									
Rat bite case									
Less cooling problem due to dirty Airfilter									
Remote setting changed									
Clogged Condenser									
Other - Pl. specify									

DAIKIN
403

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS

 Office No. 108 & 109, Devashree Garden, Commercial Complex,
 R.W. Swant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
 Mob.: 9322334107 / 9322334109

 Subject: **Installation**

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				F1602					
User: Bajaj housing finance Ltd. Mobile:				Operation data (Ambient temp. °C)				Fault Diagnosed	
Customer Address: B 101 1st Floor Polaris, off marol				Before repair		After repair		✓	
Base Address: maroshi road, marol, Andheri east				HP / T		pslg/		PSB	
Daikin Invoice: _____ Date: _____				SP / T °C		pslg/°C		EM	
Dealer Invoice: _____ Date: _____				Current °C		Amps °C		Comp	
Type	Model No	Manufacturing No.		Voltage	Volts	Volts		Electrical	
Outdoor unit /	RKMSOUV16VA	8233960		Indoor temperature					
Indoor unit	FTKMSOUV16VA	8196827		Suction	°C	°C		Unit	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge	°C	°C	
13				Installation Done. Now		Outdoor temperature		Installation	
07				A.C working cooling		Suction	°C	°C	
25				Fine		Discharge	°C	°C	
Compressor manufacturing No.				Defective Compressor		Replacement Compressor		Other	
Installed date		Warranty	AMC	Using with	Fault location	Phenomena code	Error code	Details of Repair Work Done	
Yes / No		Yes / No	Yes / No	Yes / No	Yes / No			✓	
Service Engineer Remarks									
Name F1602 + Abid									
Customer Remarks									
Name Abhi Jeet S. Mohite									
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									