

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT :- Adi Sports India Pvt Ltd Ground Floor, 162/3, Fatehchand Damani Nagar, Station Road, Solapur-413001.

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Open Area	Cassette	3 TR	FCQF36ARV16	0030635	RGVF36ASV16	0029874	25	28	(32 MM) 41 RMT	Fabrication
2											
3	Open Area	Cassette	3 TR	FCQF36ARV16	0030636	RGVF36ASV16	0029823	25.3	28.3		
4											
5	Open Area	Cassette	3 TR	FCQF36ARV16	0030643	RGVF36ASV16	0029883	24	27		
6											
7	Open Area	Cassette	3 TR	FCQF36ARV16	0030633	RGVF36ASV16	0029768	20	23		
8											

CIVIL WORK	Stabilizer			TIMER	CORE CUTTING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
-	-	-	-	-	-	100*50	-	-	-	-
-	-	-	-	-	-	22.5 RMT	-	-	-	-

OTHERS Outdoor Unit Lifting, Shifting and Placement using Crane along with Mathadi Labour Charges for 8 Nos.

For Customer Details : Adi Sports India Pvt Ltd	Vendor Details : AEON AIRCONDITIONING SOLUTIONS
Sign :	Signature :
Name :	Technician Name : Malik Maniyar
For Customer Stamp :	Date :

Adidas Outlet
 Adisports Ind Pvt. Ltd
 Jamshid Realty Ltd.
 Shop no:- Ground Floor, 162/3,
 Fatehchand Damani Nagar,
 Station Road, Solapur-413001
 GST :- 27AABCC3613G123

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT :- Adi Sports India Pvt Ltd Ground Floor, 162/3, Fatehchand Damani Nagar, Station Road, Solapur-413001.

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Open Area	Cassette	3 TR	FCQF36ARV16	0030404	RGVF36ASV16	0029849	26.3	29.3	(40 MM) 53 RMT	Fabrication
2											
3	Open Area	Cassette	3 TR	FCQF36ARV16	0030689	RGVF36ASV16	0029902	24.7	28		
4											
5	Open Area	Cassette	3 TR	FCQF36ARV16	0030634	RGVF36ASV16	0029901	21	24		
6											
7	Open Area	Cassette	3 TR	FCQF36ARV16	0030644	RGVF36ASV16	0029769	28.3	31.3		
8											

CIVIL WORK	Stabilizer			TIMER	CORE CUTTING	CABLE TRAY	DRAIN PUMP	DISMENTALING		RE-INSTALLATION	
	3KVA	4KVA	5KVA					Hi Wall	Cassette		
						200*50					
						27.5 RMT					
OTHERS	MS Fabrication Mounting Frame with Threaded Rod Supports for Cassette AC indoor unit - 8 Nos.										
For Customer Details:	Adi Sports India Pvt Ltd					Vendor Details: AEON AIRCONDITIONING SOLUTIONS					
Sign:						Signature:					
Name:						Technician Name: Malik Maniyar					
For Customer:	Stamp:					Date:					

Handwritten signature/initials.

Adidas Outlet
Adisports Ind Pvt. Ltd
Jamshri Realty Ltd.
Shop no:- Ground Floor, 162/3,
Fatehchand Damani Nagar,
Station Road, Solapur-413001
GST :- 27AABCC35130123

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS
Shop No. 6 & 7, Aash House, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (022)3341187, 692234103

Subject: Adi Sports India Pvt Ltd		Request Date: _____		Service Engineer: Ashuq		Scheduled Date/Time: _____		Service Order: _____	
User: Fatehchand Damani Customer Address: Nagar Station Road Solapur 413001				Operation data (Ambient temp. °C)				Fault Diagnosed	
I Block Address: _____				Before repair		After repair		<input checked="" type="checkbox"/> Power Failure <input type="checkbox"/> Phase Reverse <input type="checkbox"/> In door unit PCB Defective <input type="checkbox"/> Out door PCB Defective <input type="checkbox"/> In door unit Fan Motor Defective <input type="checkbox"/> Outdoor Fan Motor Defective <input type="checkbox"/> Compressor High Current / Amp <input type="checkbox"/> Compressor Ground / Earth <input type="checkbox"/> Compressor Tripping due to High Temperature <input type="checkbox"/> Compressor tripping due to High Pressure <input type="checkbox"/> Indoor Unit High Pressure Defective <input type="checkbox"/> Outdoor Unit High Pressure Defective <input type="checkbox"/> Indoor Unit Transformer Faulty <input type="checkbox"/> Outdoor Unit Transformer Faulty <input type="checkbox"/> Fault of swing factor <input type="checkbox"/> Defect of Drain Pump <input type="checkbox"/> Expansion Valve Faulty / Error Defective <input type="checkbox"/> Defective Temperature Sensor of Indoor Unit <input type="checkbox"/> Defective Temperature Sensor of Outdoor Unit <input type="checkbox"/> Defective Current Sensor in Outdoor Unit <input type="checkbox"/> Gas Leakage at Indoor Unit <input type="checkbox"/> Gas Leakage at Outdoor Unit <input type="checkbox"/> Blower lock-in <input type="checkbox"/> Short Cycling of Air at Indoor Unit <input type="checkbox"/> Short Cycling of Air at Outdoor Unit <input type="checkbox"/> Defect in cable being system <input type="checkbox"/> Gas Leakage from Filter unit <input type="checkbox"/> Error in Transmission wiring <input type="checkbox"/> Reduced outdoor capacity <input type="checkbox"/> R410a gas <input type="checkbox"/> Less cooling problem due to dirty Airfilter <input type="checkbox"/> Remote setting changed <input type="checkbox"/> Chopped Condenser <input type="checkbox"/> Other - PL specify	
Date: _____ Dealer Invoice: _____ Date: _____				HP/RT: _____		SP/RT °C: _____		Compt °C: _____	
Type: _____ Model No: KRVT36ARV16 Manufacturing No: 0024768 Indoor unit: FCQF36ARV16 Outdoor unit: 0030633				Voltage: _____		Indoor temperature: _____		Outdoor temperature: _____	
Work Date: _____ No. of S.E.: _____ Work Progressed: _____ Hours: _____				Suction: _____		Discharge: _____		Work No / Parts No: _____	
Details of the Repair Work: AC Installation work completed.				Suction: _____		Discharge: _____		Qty: _____	
Compressor manufacturing No: _____ Outdoor Compressor: _____ Replacement Compressor: _____				Total: _____		Billing Amount: _____		<input checked="" type="checkbox"/> Details of Repair Work Done <input type="checkbox"/> Single Repair <input type="checkbox"/> Part Replaced <input type="checkbox"/> Part Replaced <input type="checkbox"/> Gas Charging done <input type="checkbox"/> Recharge Service - Wet <input type="checkbox"/> Recharge Service - Dry	
Installing water: _____ Warranty: _____ AMC: _____ Using with Stabilizer: _____ Fault location: _____ Phenomena: _____ Error code: _____				Signature: Ashuq		Signature: _____		Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent) How is the behavior of your engineer: _____ What is the level of your satisfaction: _____ How is the assistance by Engineer: _____	
Service Engineer Remarks: AC working & cooling properly.				Signature: _____		Signature: _____		Customer Remarks: Name: _____ Signature: _____	

Daikin Customer Care : Missed Call or SMS - 0201014-1092101 00999 ; Toll Free Number : 1800 22 9500 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

Ashuq

Adidas Outlet
Adisports Ind Pvt. Ltd
Jamshin Realty Ltd.
Shop no:- Ground Floor, 162/3,
Fatehchand Damani Nagar,
Station Road, Solapur-413001
GST :- 27AABCC3513G123

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS
Unit No. S.A.7, Aamh Tower, 1st, Keshavnagar Rd., Thane (W)
Phone: +91 (22)25341077/422254154

Requester Name Bdi Sports India Pvt Ltd		Request Date		Service Engineer Madik Maniyar		Scheduled Date/Time		Service Order	
Unit No. Fatechand Damani Nagar Station Road Solapur-413001		Operation data (Ambient temp. °C)		Before repair		After repair		Fault Diagnosed	
Type		HP/T		psh/°C		psh/°C		Power Failure	
Date of purchase		SP/T/°C		psh/°C		psh/°C		Piston Reverse	
Capacity (Tons)		Current/°C		Amps/°C		Amps/°C		Indoor unit PCB Defective	
Type		Voltage		Volts		Volts		Out door PCB Defective	
Model No. KGVF36ARV16		Manufacturing No. 0024769		Voltage		Volts		Indoor Unit Fan Motor Defective	
Model No. FGSF36ARV16		Manufacturing No. 0030644		Voltage		Volts		Outdoor Fan Motor Defective	
Work Date		Discharge		°C		°C		Compressor Running due to High Temperature	
No. of hours		Suction		°C		°C		Compressor Running due to High Pressure	
Prog. No.		Discharge		°C		°C		Indoor Unit Mgmt Defective	
Prog. No.		Suction		°C		°C		Outdoor Unit Mgmt Defective	
Prog. No.		Discharge		°C		°C		Indoor Unit Transformer Faulty	
Prog. No.		Suction		°C		°C		Outdoor Unit Transformer Faulty	
Prog. No.		Discharge		°C		°C		Fault of wiring factor	
Prog. No.		Suction		°C		°C		Defect of Drain Pump	
Prog. No.		Discharge		°C		°C		Expansion Valve Body / Motor Defective	
Prog. No.		Suction		°C		°C		Compressor Temperature Sensor of Indoor Unit	
Prog. No.		Discharge		°C		°C		Defective Temperature Sensor of Outdoor Unit	
Prog. No.		Suction		°C		°C		Defective Gas Sensor in Out door Unit	
Prog. No.		Discharge		°C		°C		Gas Leakage at Indoor Unit	
Prog. No.		Suction		°C		°C		Gas Leakage at Outdoor Unit	
Prog. No.		Discharge		°C		°C		Blower broken	
Prog. No.		Suction		°C		°C		Short Cycling of Air at Indoor Unit	
Prog. No.		Discharge		°C		°C		Short Cycling of Air at Outdoor Unit	
Prog. No.		Suction		°C		°C		Defect in Drain piping system	
Prog. No.		Discharge		°C		°C		Gas Leakage from Flare nut	
Prog. No.		Suction		°C		°C		Error in Freon emission wiring	
Prog. No.		Discharge		°C		°C		Product under capacity	
Prog. No.		Suction		°C		°C		Rubbish case	
Prog. No.		Discharge		°C		°C		Less cooling problem due to dirty Airfilter	
Prog. No.		Suction		°C		°C		Remote setting changed	
Prog. No.		Discharge		°C		°C		Charged Gas sensor	
Prog. No.		Suction		°C		°C		Other - PK Ready	
Prog. No.		Discharge		°C		°C		Details of Repair Work Done	
Prog. No.		Suction		°C		°C		Simple Repair	
Prog. No.		Discharge		°C		°C		Part Replaced	
Prog. No.		Suction		°C		°C		Part Replaced	
Prog. No.		Discharge		°C		°C		Gas Charging done	
Prog. No.		Suction		°C		°C		Refrigerant Service - Wet	
Prog. No.		Discharge		°C		°C		Refrigerant Service - Dry	
Prog. No.		Suction		°C		°C		Total	
Prog. No.		Discharge		°C		°C		Customer Impression about Service	
Prog. No.		Suction		°C		°C		(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)	
Prog. No.		Discharge		°C		°C		How is the behavior of visited engineer	
Prog. No.		Suction		°C		°C		How is the level of your satisfaction	
Prog. No.		Discharge		°C		°C		How is the explanation by Engineer	

Daikin Customer Care : Missed Call or SMS «DAIKIN» to 02101 86559 ; Toll Free Number : 1800 22 9300 / 1800 102 9300 ; ea@daikin.co.in / www.daikin.co.in

Handwritten signature

Adidas Outlet
Adisports Ind Pvt. Ltd
Jamshri Realty Ltd.
Shop no:- Ground Floor, 162/3,
Fatechand Damani Nagar,
Station Road, Solapur-413001
GST :- 27AABCC3513G1Z3

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS
Shop No. A-3, Aeon Hitech, Dr. Ambedkar Rd., Thane (W)
Phone : +91 (022)2541077, 640034169

Subject: Adi Sports India Pvt Ltd		Registration No.		Repair Date		Service Engineer		Scheduled Date/Time		Service Order	
User: Fatechand Damani Nagers		Customer Address: Station Road Solapur - 413001		Date: _____		Time: _____		City: _____		State: _____	
Opinion data (Ambient temp. °C)		Before repair		After repair		Before repair		After repair		Fault Diagnosed	
HT/T	psi/°C	psi/°C	psi/°C	psi/°C	psi/°C	Indoor Temp	°C	Indoor Temp	°C	<input type="checkbox"/>	<input checked="" type="checkbox"/>
SP/T	psi/°C	psi/°C	psi/°C	psi/°C	psi/°C	Outdoor Temp	°C	Outdoor Temp	°C	<input type="checkbox"/>	<input type="checkbox"/>
Compt	°C	Amps	°C	Amps	°C	Discharge	°C	Discharge	°C	<input type="checkbox"/>	<input type="checkbox"/>
Volage	Volts	Volts	Volts	Volts	Volts	Section	°C	Section	°C	<input type="checkbox"/>	<input type="checkbox"/>
Type: _____		Model No: RGVF36ARV16		Manufacturing No: 004902		Work No / Part No		City		Billing Amount	
Date of Installation: _____		Warranty: _____		Remarks: _____		Work No / Part No		City		Billing Amount	
AC Installation work completed.		AC working & cooling properly.		Signature: Mulile Muniyasa		Work No / Part No		City		Billing Amount	
Customer Remarks		Customer Impression about Service		Signature: _____		Work No / Part No		City		Billing Amount	
Name: _____		Name: _____		Signature: _____		Work No / Part No		City		Billing Amount	
Name: _____		Name: _____		Signature: _____		Work No / Part No		City		Billing Amount	

MFA

Adidas Outlet
Adisports Ind Pvt. Ltd
Jamshri Realty Ltd.
Shop no:- Ground Floor, 162/3,
Fatechand Damani Nagar,
Station Road, Solapur-413001
GST: 27A...13G123