



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601. Maharashtra

Tel. : 022 - 25370101 / 7900097007

e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project : Bajaj Finance Ltd, Raptarpadi Hall, Swapndeept Bldg, Railway Stn, Kalyan.

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Customer	Split	1.5	4TKM150UV	58689	RKM150UV	89711	16	18	3.2	L type
2	Lobby										Stand.
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
Others										

For	Vendor Details				
Sign	Signature				
Name	Technician Name				
Date	Date				

Ans. W. Kulkarni

13/01/2025

Stamp



Aeon Airconditioning Solutions.

Signature

Haizan & Umar.

13/01/2025.

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate

aeon
AEON AIRCONDITIONING SOLUTIONS

1250

 Office No. 108 & 109, Devashree Garden, Commercial Complex,
 R.W. Swarni Marg, above Sheetal Dairy, Fluru Park, Thane - 400 601.
 Mob.: 9322334107 / 9322334108
Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order			
User: <u>Bajaj finance ltd.</u>		Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed					
Customer Address: <u>Bajaj finance, Septapadi Hall,</u>				Before repair		After repair		Power			
Base Address: <u>Swarnadeep Bldg, Railway Stn. Korjat.</u>				HP / T		psig/		PCB			
Daikin Invoice:		Date:		SP / T °C		psig/°C		EM			
Dealer Invoice:		Date:		Current °C		Amps°C		Comp			
Type	Model No	Manufacturing No.		Voltage		Volts		Electrical			
Outdoor unit /	<u>RKM50UV16UA</u>	<u>89711</u>		Indoor temperature				Unit			
Indoor unit	<u>TKRM50UV16UA</u>	<u>58689</u>		Suction		°C		Installation			
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		Other			
<u>13</u>				<u>A/C Installation done</u>		Outdoor temperature		Details of Repair Work Done			
<u>01</u>				<u>How all working</u>		Suction					
<u>2025</u>				<u>& Cooling fine</u>		Discharge					
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty			
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code	Billing Amount				
	Yes / No	Yes / No	Stabilizer	Cut off							
Service Engineer Remarks		Yes / No		Yes / No	Yes / No	Yes / No	Total				
<u>Main power supply not given by Customer. (pending by Customer)</u>											
Name <u>Faizan & Umar</u>		Signature <u>Faizan</u>									
Customer Remarks		AC. installation done but main power supply not installed									
Name <u>Amis. Kaur</u>		Signature <u>Amis. Kaur</u>									
Customer Impression about Service		(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer											
What is the level of your satisfaction											
How is the explanation by Engineer											
a Simple Repair											
b Part Replaced											
c Part Repaired											
d Gas Charging done											
e Routine Service - Wet											
f Routine Service - DRY											