



DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Provider

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6 & 7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007 / 9322334106



PROJECT :- Craftsman villas

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Hall office	2.5 ton		FCVF71QRV169	2804	12VF7113RV169	3783	12 mtr	13 mtr		
2											
3											
4											
5											
6											
7											
8											
9											
10											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
									✓	
									1	
OTHERS										

For Customer Details :

Sign :	<u>[Signature]</u>	Vendor Details :	
Name :	<u>Somnath Sahu</u>	Signature :	<u>[Signature]</u>
Date :	<u>23/06/25</u>	Technician Name :	<u>Agha</u>
		Date :	<u>23-06-25</u>



011

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject : Tabulation

Subject:		Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
Installation						A9her					
User: Craftsman Automation Ltd. Mobile:				Operation data (Ambient temp. °C)				Fault Diagnosed			
Customer Address: 306 Saswanti Lungsaric LBS RD											
Base Address: Viriboli (W)											
Daikin Invoice:				Date:							
Dealer Invoice:				Date:							
Type		Model No		Manufacturing No.		Voltage		Volts		Volts	
Outdoor unit /		12VF71A3RV164		3783		Indoor temperature					
Indoor unit		CCVF71ARV164		2804		Suction		°C		°C	
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work		Discharge	
23/06/25								A.C Installation Done Now A.C working and cooling fine.		°C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty		Billing Amount	
Installed date		Warranty		AMC		Using with		Fault location		Phenomena code	
		Yes / No		Yes / No		Stabilizer Cut off				Error code	
Service Engineer Remarks											
Name: A9her - J. Pair Signature: [Signature]											
Customer Remarks: AC is under observation for cooling.											
Customer Impression about Service (Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)											
How is the behavior of visted engineer											
What is the level of your satisfaction											
How is the explanation by Engineer											
a Simple Repair											
b Part Replaced											
c Part Repaired											
d Gas Charging done											
e Routine Service - Wet											
f Routine Service - DRY											