



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dhyan Mandir
Dr. Ambedkar Rd, Thane 400 601, Maharashtra
Tel. : 022 - 25370101 / 7900097007
e-mail: services@aeonacsolutions.com website: www.aeonacsolutions.com

Project: Eat club food Ltd - Kamjur mang

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1		Split	1.5	FTKLS0UV	8040875	RKL50UV16	8160495	-	-	-	-
2				16VAF		VAF					
3											
4											
5											
6											
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
Stand-Point Coating - 1 Nos										
Others	Nitrogen Flushing & Vacuuming									
For	Vendor Details Aeon Airconditioning Solutions									
Sign	Signature					Firoz + Rehan				
Name	Technician Name					23/04/25				
Date	Date									

Stamp

(N. Kohale)

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS
496

 Office No. 108 & 109, Devashree Garden, Commercial Complex,
 H.V. Swarn Marg, above Sheela Dairy, Rishi Park, Thane - 400 601
 Mob. : 9322334107 / 9322334109

Subject: Installation		Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order		
User: Eat Club Food Ltd.		Mobile		Operation data (Ambient temp. °C)		Fault Diagnosed						
Customer Address: Shop No 9, Ground Floor Huma				Before repair		After repair		✓				
Base Address: Mal Kanjurmarg west Mumbai				HP/T		only						
Dakus Invoice		Date		SP/T °C		only °C						
Dealer Invoice		Date		Current °C		Amps °C						
Type	Model No	Manufacturing No		Voltage		Volts						
Outdoor unit /	R1CLSL01V16VHF	8160495		Indoor temperature		Volts						
Indoor unit	FT1CLSL01V16VHF	8440375		Suction		°C						
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C				
23/04/25				Installation Done Now A/C working cooling Fine		Outdoor temperature		°C				
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Suction		°C				
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code	Discharge		°C			
	Yes / No	Yes / No	Stabilizer Cut off				Work hrs / Parts No		Qty		Billing Amount	
	Yes / No	Yes / No	Yes / No				1		1			
Service Engineer Remarks		Signature		Total		Other		Unit				
Fixed + Rehan												
Customer Remarks		Signature		Code		Details of Repair Work Done		✓				
Customer Impression about Service		(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		How is the behavior of visited engineer		a		Single Repair				
				What is the level of your satisfaction		b		Part Replaced				
				How is the explanation by Engineer		c		Part Replaced				
						d		Gas Charging done				
						e		Routine Service - Yes				
						f		Routine Service - NO				