



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
 Dr. Ambedkar Rd Thane 400 601 Maharashtra
 Tel: 022 - 25370101 / 7900097007
 e-mail: services@aeonacsolutions.com website: www.aeonacsolutions.com

308

Project: Subway Kala Ghoda

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	Work Area	Cassette AC	3.0TR	FTKL60UV16V	8018543	RKL60UV16V	8027789	4	16	10	
2	Work Area	Cassette AC	3.0TR	FCVFR71AV16	0014019	R2VFR71AV16	0014083	11	13	7	
3	Work Area	Split AC	2.0TR	FTKL60UV16V	8019061	RKL60UV16V	8027786	12	14		
4	Store Room	Split AC	2.0TR	FTKL60UV16V	8018517	RKL60UV16V	8027793	4	6		
5	Store Room	Split AC	2.0TR	FTKL60UV16V	8018543	RKL60UV16V	8027789	3	5		
6	Work Area	Cassette AC	3.0TR	FCVFR71AV16	0013579	R2VFR71AV16	6013036	14	16	10	
7											
8											

Extra Activity Carried Out

Civil Work	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
Core Cutting										
Others	<u>Refrigeration stand</u>									

For	Subway		Vendor Details
Sign	<u>[Signature]</u> 75238-1-0 Kala Ghoda Mumbai Eversub India Private Limited		Signature
Name	Project S. Moini Shop No. 2, Parekh-Vora Chambers, Nagindas Master Road, Opp. Theoberoma Kala Ghoda, Fort, Mumbai, Stamp: Thane - 400 001.		Technician Name
Date	13/12/24		Date
			Akram
			13-12-25

318 DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate

AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Sawaant Marg, above Sheetal Dairy, Rulu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order			
		13-12-25		Akram							
User : Subway Customer Address : Kala Ghoda I Base Address : churdgate			Mobile :			Operation data (Ambient temp. °C)			Fault Diagnosed		
Daikin Invoice : Dealer Invoice :			Date :			SP / T °C			Power Failure <input checked="" type="checkbox"/>		
Type			Model No			Manufacturing No.			Phase Reverse		
Outdoor unit / Indoor unit			RkL60UV16V FKL60UV16V			8027793 8018514			In door unit PCB Defective		
Work Date			No. of S.E.			Work hours			Progress code		
13									In door unit Fan Motor Defective		
12									Outdoor Fan Motor Defective		
25									Comp. taking High Current / Amp		
Details of the Repair Work			2.0 TR Daikin split A/C Installation is done			Current °C			Compressor Ground / Earth		
Compressor manufacturing No.			Defective Compressor			Replacement Compressor			Compressor tripping due to High Temperature		
Installed date			Warranty			AMC			Compressor tripping due to High Pressure		
			Yes / No			Yes / No			Indoor Unit MgsW Defective		
Service Engineer Remarks			cooling is fine			Using with Stabilizer			Outdoor Unit MgsW Defective		
Name Akram			Signature			Fault location			Indoor Unit Transformer Faulty		
Customer Remarks			Store Name Kala Ghoda			Phenomena code			Out door Unit Transformer Faulty		
Name Raveet			Signature			Error code			Fault of swing Motor		
Customer Impression about Service			Goods Recd. Date			Work No / Parts No			Defect of Drain Pump		
How is the behavior of visited engineer			Goods Recd. Time			Qty			Expansion Valve Body / Motor Defective		
What is the level of your satisfaction			Signature			Billing Amount			Defective Temperature Sensor of Indoor Unit		
Is the explanation by Engineer			Signature			Total			Defective Temperature Sensor of Outdoor Unit		
Details of Repair Work Done			Signature						Defective Current Sensor in Out door Unit		
a Simple Repair									Gas Leakage at Indoor Unit		
b Part Replaced									Gas Leakage at Outdoor Unit		
c Part Repaired									Blower broken		
d Gas Charging done									Short Cycling of Air at Indoor Unit		
e Routine Service - Wet									Short Cycling of Air at Outdoor Unit		
f Routine Service - DRY									Defect in Drain piping System		

Eversub India Pvt. Ltd.
Store Name Kala Ghoda
City Mumbai
Goods Recd. Date
Goods Recd. Time
Signature
Site/Project Engg. Sign

DAIKIN

317 DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Svaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order		
		13-12-25		Akram						
User: <u>Subway</u>				Mobile:		Operation data (Ambient temp. °C)				
Customer Address: <u>Kalaghada</u>						Before repair		After repair		
I Base Address: <u>Churchgate</u>						HP / T		psig/		
Daikin Invoice:				Date:		SP / T °C		psig/°C		
Dealer Invoice:				Date:		Current °C		Amps°C		
Type		Model No		Manufacturing No.		Voltage		Volts		
Outdoor unit /		<u>RKL60UU16V</u>		<u>8027786</u>		Indoor temperature				
Indoor unit		<u>FTKL60UU16V</u>		<u>8019061</u>		Suction		°C		
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work				Discharge		
<u>13</u>				<u>200TR Daikin split AC</u>				°C		
<u>12</u>				<u>Installation is done</u>				°C		
<u>25</u>								°C		
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty		
Installed date	Warranty	AMC	Using with Stabilizer	Fault location	Phenomena code	Error code	Billing Amount		Unit	
	Yes / No	Yes / No	Yes / No	Yes / No					Electrical	
Service Engineer Remarks: <u>Cabling is fine</u>							Total		Installation	
									Other	
Name: <u>Dhruv</u>									Details of Repair Work Done	
Customer Remarks: <u>Store Name Kalaghada</u>									a Simple Repair	
City: <u>Mumbai</u>									b Part Replaced	
Goods Recd. Date: <u>[Signature]</u>									c Part Repaired	
Goods Recd. Time: <u>[Signature]</u>									d Gas Charging done	
Name: <u>Ranjit</u>									e Routine Service - Wet	
Site/Project Engg. Sign: <u>[Signature]</u>									f Routine Service - DRY	

Daikin Customer Care : Missed Call 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

DAIKIN

316

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Dewashree Garden, Commercial Complex,
R.W. Svaant Marg, above Sheetal Dairy, Rulu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
		13-12-25		Akram					
User : <i>Subhney</i>		Mobile :		Operation data (Ambient temp. °C)		Fault Diagnosed			
Customer Address : <i>Kala glada chivolate</i>				Before repair		After repair		Power Failure	
I Base Address :				HP / T		psig/ psig/		Phase Reverse	
Daikin Invoice :		Date :		SP / T °C		psig/°C psig/°C		In door unit PCB Defective	
Dealer Invoice :		Date :		Current °C		Amps°C Amps°C		Out door PCB Defective	
Type		Model No		Manufacturing No.		Voltage		Indoor temperature	
Outdoor unit /		<i>R2VFQ7HAU16</i>		<i>0014033</i>		Volts		Suction °C °C	
Indoor unit		<i>FCVFA7HAU16</i>		<i>0014014</i>		Volts		Discharge °C °C	
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work	
<i>13</i>		<i>12</i>		<i>25</i>				<i>3.0TR Daikin Cassette A/c Installation Done</i>	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
Installed date		Warranty		AMC		Using with Stabilizer		Cut off	
Yes / No		Yes / No		Yes / No		Yes / No		Yes / No	
Service Engineer Remarks		<i>Cooling is fine</i>		Signature		Name		<i>Akram</i>	
Customer Remarks		Store Name <i>Kala Glada</i>		City <i>Mumbai</i>		Goods Recd. Date		Signature	
Name		<i>Ranjit</i>		Goods Recd. Time		Site/Project Engg. Name		<i>Ranjit</i>	
Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1 800 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com		Site/Project Engg. Sign		Customer Impression about Service		a Simple Repair		b Part Replaced	
				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		c Part Repaired		d Gas Charging done	
				How is the behavior of visited engineer		e Routine Service - Wet		f Routine Service - DRY	
				What is the level of your satisfaction		How is the explanation by Engineer		Details of Repair Work Done	
								✓	



315 DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS
Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Ritu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order			
		13-12-25		Akram							
User : Subway			Mobile :			Operation data (Ambient temp. °C)			Fault Diagnosed		
Customer Address : Kala Ghoda			I Base Address : Churchgate			Before repair			After repair		
Daikin Invoice :			Date :			HP / T			Power		
Dealer Invoice :			Date :			psig/			Phase Reverse		
Type			Model No			SP / T °C			PCB		
Outdoor unit /			R2VFQ7HANK 0013036			psig/°C			In door unit PCB Defective		
Indoor unit			FCVFG7IAUIG 0013519			psig/°C			Out door PCB Defective		
Work Date			No. of S.E.			Current °C			EM		
13						Amps°C			In door unit Fan Motor Defective		
12						Amps°C			Comp. taking High Current / Amp		
25						Volts			Compressor Ground / Earth		
Details of the Repair Work			3.0 TR Daikin Cassette A/C Installation done			Voltage			Comp		
Discharge						Volts			Compressor Tripping due to High Temperature		
Suction						Indoor temperature			Compressor tripping due to High Pressure		
Discharge						°C			Indoor Unit MgsW Defective		
Suction						°C			Outdoor Unit MgsW Defective		
Discharge						°C			Indoor Unit Transformer Faulty		
Work No / Parts No			Qty			Billing Amount			Out door Unit Transformer Faulty		
Total									Fault of swing Motor		
Compressor manufacturing No.			Defective Compressor			Replacement Compressor			Electrical		
Installed date			Warranty			AMC			Unit		
Yes / No			Yes / No			Yes / No			Gas Leakage at Indoor Unit		
Using with Stabilizer			Cut off			Fault location			Gas Leakage at Outdoor Unit		
Yes / No			Yes / No			Phenomena code			Blower broken		
Error code									Short Cycling of Air at Indoor Unit		
Service Engineer Remarks			Cooling is fine						Short Cycling of Air at Outdoor Unit		
Name Akram			Signature			Eversub India Pvt. Ltd.			Detect in Drain piping System		
Customer Remarks			Store Name Kala Ghoda			Customer Impression about Service			Gas Leakage from Flare nut		
Name Rajeev			Signature			a Simple Repair			Error in Transmission wiring		
Goods Recd. Date			Goods Recd. Time			b Part Replaced			Product under capacity		
Site/Project Engg. Name			Signature			c Part Repaired			Rat bite case		
Site/Project Engg. Sign						d Gas Charging done			Less cooling problem due to dirty Airfilter		
						e Routine Service - Wet			Remote setting changed		
						f Routine Service - DRY			Clogged Condenser		
									Other - Pl. specify		
									Details of Repair Work Done		
									✓		

Daikin Customer Care : Missed Call or SMS to DAIKIN to 92101-09999, Toll Free Number : 1800 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com