

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Authorised Service Center

AEON AIRCONDITIONING SOLUTIONS

AEON HOUSE, SHOP NO. 6/7, BEHIND N CUBE CHINA TOWN

DR. AMBEDKAR ROAD, THANE W 400601 MAHARASHTRA. PHONE :- 02225370101 / 7900097007



PROJECT:- ALL RMX Rajarshat West Bengal ADANI

Measurement Sheet

Sr. No.	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	AI Room	Split	2TR	FTKL60XV16VAA	8012480	RKL60XV16VAA	8016331	4m	5m	5m	—
2	QC Room	Split	2TR	FTKL60XV16VAA	8012469	RKL60XV16VAA	8016429	—	—	—	—
3	Batch Cabin	Split	2TR	FTKL60XV16VAA	8012452	RKL60XV16VAA	8016422	—	—	—	—
4											
5											
6											
7											
8											

EXTRA ACTIVITY CARRIED OUT

CIVIL WORK	Stabilizer			TIMER	CASING CAPPING	CABLE TRAY	GAS CHARGING	DISMENTALING		RE-INSTALLATION
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
								2		

OTHERS Two old AC uninstall

For Customer Details: ACC Ltd ADANI

Vendor Details: AEON AIRCONDITIONING SOLUTIONS

Sign: [Signature]

Signature: [Signature]

Name: Sonar Dhara

Technician Name: SK Nazibul Hossain

Date: 15/06/26


Stamp:

Date: 15/06/26



DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

 Office No. 108 & 109, Dewashree Garden, Commercial Complex,
 R.W. Swarni Marg, above Shreeal Dairy, Pudu Park, Thane - 400 601.
 Mob.: 9322334107 / 9322334109

1415

Subject:

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: ACC Ltd. RMX Rajarshah		Customer Address: West Bengal Adani.		I Base Address:		Operation data (Ambient temp. °C)		Fault Diagnosed	
Daikin Invoice:		Date:		SP / T °C		psig/°C		psig/°C	
Dealer Invoice:		Date:		Current °C		Amps °C		Amps °C	
Type	Model No	Manufacturing No.		Voltage		Volts		Volts	
Outdoor unit /	RKL60XV16VAA	8016422		Indoor temperature					
Indoor unit	FTKL60XV16VAA	8012452		Suction		°C		°C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C	
						Outdoor temperature			
						Suction		°C	
						Discharge		°C	
						Work No / Parts No		Qty	
						Billing Amount			
Compressor manufacturing No.		Defective Compressor		Replacement Compressor					
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code			
	Yes / No	Yes / No	Yes / No	Yes / No					
Service Engineer Remarks: Installation and Commissioning done now AC cooling during OK.									
Name: SA Nojibul Hossain						Signature: [Signature]			
Customer Remarks: OK									
Name: Soumya Sharma						Signature: [Signature]			
Customer Impression about Service									
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)									
How is the behavior of visited engineer									
What is the level of your satisfaction									
How is the explanation by Engineer									
a Simple Repair									
b Part Replaced									
c Part Repaired									
d Gas Charging done									
e Routine Service - Wet									
f Routine Service - DRY									
Details of Repair Work Done									



Office No. 105 & 109, Dewashree Garden, Commercial Complex,
R.W. Swamiji Marg, above Sheetal Dairy, Pusa Park, Thane - 400 601.
Mob: 9822234107 / 9822234109

1415

Subject :

[illegible]

User: ACC Ltd. Rmx Rajarshah West Customer Address: Bengel Adami Base Address:	Operation data (Ambient temp. °C)			Fault Diagnosis	
		Before repair	After repair	Power	Power Failure
				PCB	Phase Reverse
	HP / T	psig/	psig/	PCB	In door unit PCB Defective
					Out door PCB Defective
					In door unit Fan Motor Defective

Daikin Invoice :	Date :	SP / T °C	pslg °C	pslg °C	ENR	In Door Unit Fan Motor Defective
Daikin Invoice :	Date :	Current °C	Amps °C	Amps °C	P	Outdoor Fan Motor Defective Comp. taking High Current / Amp Compressor Ground / Earth

Type	Model No	Manufacturing No.	Voltage	Volts	Volts	G	Compressor tripping due to High temperature
Outdoor unit /	RKL60XV16VAA	8016331	Indoor temperature				Compressor tripping due to High Pressure
Indoor unit	FTKL60XV16VAA	8012480	Suction	°C	°C	Indoor Unit MqSw Defective	
						Outdoor Unit Mqsw Defective	
						Indoor Unit Transformer Faulty	
						Indoor Unit Transformer Faulty	

Work Date	No. of S.E	Work hours	Progress code	Details of the Repair Work	Discharge	°C	°C	Electrical	Out door Unit, Transmitter Facility
					Outdoor temperature			Electrical	Fault of swing Motor
					Suction	°C	°C		Defect of Drain Pump
					Discharge	°C	°C		Expansion Valve Body / Motor Defective
									Defective Temperature Sensor of Indoor Unit
						°C	°C		Defective Temperature Sensor of Outdoor Unit
									Defective Current Sensor In Out door Unit
					Work No / Parts No	Qty	Billing Amount	Unit	Gas Leakage at Indoor Unit
									Gas Leakage at Outdoor Unit


Compressor manufacturing No.		Defective Compressor		Replacement Compressor					Installation Blower broken Short Cycling of Air at Indoor Unit Short Cycling of Air at Outdoor Unit Defect in Drain piping System Gas Leakage from Flare nut Error In Transmission wiring Product under capacity
Installed date	Warranty	AMC	Using With		Fault location	Phenomena code	Error code		
			Stabilizer	Cut off					
	Yes / No	Yes / No	Yes / No	Yes / No					

Service Engineer Remarks	Installation and Commissioning.		Rat bite case
	done cooling running ok.		
Name	3K Mojibul Hossain	Signature	Remote setting changed
			Clogged Condenser
Total		Other - PL specify	

Customer Remarks OK			Customer Impression about Service		a	Simple Repair
Name: <u>Sonar Dhara</u> Signature: <u>[Signature]</u> Date: <u>15/06/24</u> <u>15/06/24</u>			(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		b	Part Replaced
		How is the behavior of visited engineer		c	Part Repaired	
		What is the level of your satisfaction		d	Gas Charging done	
		How is the explanation by Engineer		e	Routine Service - Wet	
		How is the explanation by Engineer		f	Routine Service - DRY	

DAIKIN

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate


AEON AIRCONDITIONING SOLUTIONS

 Office No: 108 & 109, Devastree Garden, Commercial Complex,
 R.W. Swarni Marg, above Sheetal Dairy, Pusa Park, Thane - 400 601.
 Mob: 9322334107 / 9322334109

1415

Subject:

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
User: MCC Ltd RMX Rajarshat West Bengal				Operation data (Ambient temp. °C)			Fault Diagnosed		
Customer Address: Adani.							✓		
Base Address:				Before repair			After repair		
				HP / T			psig/		
Daikin Invoice:				SP / T °C			psig/°C		
Dealer Invoice:				Current °C			Amps °C		
Date: 15/6/26				Amps °C					
Type				Voltage			Volts		
Model No				Volts					
Manufacturing No.				Indoor temperature					
Outdoor unit /				Suction			°C		
Indoor unit				Discharge			°C		
Work Date				Suction			°C		
No. of S.E.				Discharge			°C		
Work hours				Work No / Parts No			Qty		
Progress code				Billing Amount					
Details of the Repair Work				Total					
Compressor manufacturing No.				Defective Compressor			Replacement Compressor		
Installed date				Using with			Fault location		
Warranty				Stabilizer			Phenomena code		
AMC				Cut off			Error code		
Yes / No				Yes / No			Yes / No		
Service Engineer Remarks				Service Engineer Signature					
Installation and Commissioning done cooling; ok.				Signature					
Name: SK Noyrul Hossain				Signature					
Customer Remarks				Customer Impression about Service					
OK				(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)					
Name: Soumya Dhar				How is the behavior of visited engineer					
Signature				What is the level of your satisfaction					
15/06/26				How is the explanation by Engineer					
				a Simple Repair					
				b Part Replaced					
				c Part Repaired					
				d Gas Charging done					
				e Routine Service - Wet					
				f Routine Service - DRY					
				g Routine Service - DRY					
				Details of Repair Work Done			✓		

