

DAIKIN

338

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject :

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Akshay		27/10/25			
User: Azaan Shaikh				Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed	
Customer Address:						Before repair		After repair	
I Base Address: Kemps corner				HP / T		pslg/		pslg/	
Daikin Invoice:				Date:		SP / T °C		pslg/°C	
Dealer Invoice:				Date:		Current °C		Amps°C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		R1K50UV16VF		0029971		Indoor temperature			
Indoor unit		FTK50UV16VF		8104080		Suction		°C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C	
27				1.5 Ton Daikin		Outdoor temperature			
10				AC installation		Suction		°C	
25						Discharge		°C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
						Installation		1	
Installed date		Warranty		AMC		Uninstall		1	
		Yes / No		Yes / No		Copper		3 MTR	
						Cable		3 MTR	
						Total			
Service Engineer Remarks				Cooling Fine.		Billing Amount			
Name Ans				Signature					
Customer Remarks				Azaan Shaikh		Customer Impression about Service			
				27/10/25		(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)			
				Signature		How is the behavior of visited engineer			
						What is the level of your satisfaction			
						How is the explanation by Engineer			
								a Simple Repair	
								b Part Replaced	
								c Part Replaced	
								d Gas Charging done	
								e Routine Service - Wet	
								f Routine Service - DRY	
								g	
								h	
								i	
								j	
								k	
								l	
								m	
								n	
								o	
								p	
								q	
								r	
								s	
								t	
								u	
								v	
								w	
								x	
								y	
								z	