



AEON AIRCONDITIONING SOLUTIONS

Aeon House, Shop No. 6/7, Behind N Cube China Town, Opp. Shishu Dnyan Mandir,
Dr. Ambedkar Rd. Thane 400 601, Maharashtra
Tel. : 022 - 25370101 / 7930097007
e-mail : services@aeonacsolutions.com website : www.aeonacsolutions.com

Project : ICICI Bank Pale Ambernath

Additional Measurement Sheet

Sr. No	Location	AC Type	Tonnage	Indoor Unit Details		Outdoor Unit Details		Copper In Rmt	Cable In Rmt	Drain In Rmt	ODU Stand
				Model No.	Sr. No.	Model No.	Sr. No.				
1	B.m Cabin	Split	0.1	FTKM35UV/6 wa	366S	RKM35UV/6 wa	3111	22.5	23.7	2.1	1
2	Server Room	Split	0.1	FTKM35UV/6 wa	3684	RKM35UV/6 wa	3169	22.2	23.4	3.0	1
3	Server Room	Split	0.1	FTKM35UV/6 wa	3318	RKM35UV/6 wa	3099	21.3	22.5	2.1	1
4	ATM	Split	0.1	FTKM35UV/6 wa	3664	RKM35UV/6 wa	3168	19.5	20.7	2.1	1
5	ATM	Split	0.1	FTKM35UV/6 wa	3685	RKM35UV/6 wa	3164	22.2	23.4	5.1	1
6	Bank Entry	Cassette	1.5	ECMF71AR L169	3744	R2MF71BR L169	3796	17.9	19.2	5.4	1
7	Front Desk	Cassette	1.5	ECMF71AR L169	3741	R2MF71BR L169	3784	20.4	21.6	4.5	1
8								146	154.5	24.3	07

Extra Activity Carried Out

Civil Work Chesling	Stabilizer			Timer	Casing Capping	Cable Tray	Gas Charging	Dismantling		Re-installation
	3KVA	4KVA	5KVA					Hi Wall	Cassette	
12 mtrs.				02			01			
Others										

For	Vendor Details		
Sign	Signature		
Name	Technician Name		
Date	Date		

08-01-25

Sandip Bhoir (IFM)

Stamp

Aeon Airconditioning solutions

Firoz Hashmi

02/01/2025

Qty.

Total rmt = 126 meter
Total cable = 130 meter



DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swamiji Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

399

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Fryoz					
User: <u>ICICI Bank</u>				Mobile:		Operation data (Ambient temp. °C)			
Customer Address: <u>Raj Nirvana Shop No. 15, 16</u>						Before repair		After repair	
Base Address: <u>Anand Arceland, Pule Road.</u>						HP / T		psig/	
Daikin Invoice:				Date:		SP / T °C		psig/°C	
Dealer Invoice:				Date:		Current °C		Amps°C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		<u>R2MF71BRV169</u>		<u>3789</u>		Indoor temperature			
Indoor unit		<u>FCMF71ARV169</u>		<u>3741</u>		Suction		°C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C	
<u>02</u>				<u>Installation Done</u>		Suction		°C	
<u>02</u>				<u>New A/C Working</u>		Discharge		°C	
<u>25</u>				<u>Cooling Fine</u>		Work No / Parts No		Qty	
Compressor manufacturing No.				Detective Compressor		Replacement Compressor		Billing Amount	
Installed date		Warranty	AMC	Using with Stabilizer	Cut off	Fault location	Phenomena code	Error code	
		Yes / No	Yes / No	Yes / No	Yes / No				
Service Engineer Remarks									
Name		Fryoz		Signature		Total			
Customer Remarks									
Name		Signature		Code		Details of Repair Work Done		✓	
Customer Impression about Service						a Simple Repair			
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)						b Part Replaced			
How is the behavior of visited engineer						c Part Repaired			
What is the level of your satisfaction						d Gas Charging done			
How is the explanation by Engineer						e Routine Service - Wet			
						f Routine Service - DRY			

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swamiji Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mobi: 9322334107 / 9322334109

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				F. 602					
User: ICICI Bank				Mobile:		Operation data (Ambient temp. °C)			
Customer Address: Raj Nigvana Shop No 15, 16						Before repair		After repair	
(Base Address: Anand Greenland Pale Road)						HP / T		psig/	
Daikin Invoice:				Date:		SP / T °C		psig/°C	
Dealer Invoice:				Date:		Current °C		Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts	
Outdoor unit /		R2MFA1BRV169		3796		Indoor temperature			
Indoor unit		ECME21ARV169		3744		Suction		°C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work					
02				Installation Done					
01				New A/C working					
29				Cooling Fine					
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty	
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code	Billing Amount		Unit
	Yes / No	Yes / No	Stabilizer Cut off						Gas Leakage at Indoor Unit
									Gas Leakage at Outdoor Unit
Service Engineer Remarks									Blower broken
Name: F. 602									Short Cycling of Air at Indoor Unit
Signature: [Signature]									Short Cycling of Air at Outdoor Unit
									Defect in Drain piping System
									Gas Leakage from Flare nut
									Error in Transmission wiring
									Product under capacity
									Rat bite case
									Less cooling problem due to dirty Airfilter
									Remote setting changed
									Clogged Condenser
									Other - Pl. specify
Customer Remarks							Total		Details of Repair Work Done
									a Simple Repair
									b Part Replaced
									c Part Repaired
									d Gas Charging done
									e Routine Service - Wet
									f Routine Service - DRY
Name							Signature		

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; es@daikinindia.com / www.daikinindia.com

DAIKIN AIRCONDITIONING INDIA PVT. LTD. Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swam Marg, above Sheetal Dairy, Ruti Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order				
				Firoz								
User: <u>ICICI Bank</u>				Mobile:		Operation data (Ambient temp. °C)						
Customer Address: <u>Raj Nirvana Shop No. 15, 16.</u>						Before repair		After repair				
Base Address: <u>Amara Greenland Park Road.</u>						HP / T		pslg/ pslg/				
Daikin Invoice:				Date:		SP / T °C		pslg °C pslg °C				
Dealer Invoice:				Date:		Current °C		Amps °C Amps °C				
Type	Model No.		Manufacturing No.		Voltage		Volts		Volts			
Outdoor unit /	<u>R1cm35uvigwn</u>		<u>3104</u>		Suction		°C		°C			
Indoor unit	<u>FT1cm35uvigwn</u>		<u>3685</u>		Discharge		°C		°C			
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work				Discharge		°C		
<u>02/02/25</u>				<u>Installation Done</u>				Suction		°C		
				<u>Now A/C working</u>				Discharge		°C		
				<u>Cooling Fine</u>				Work No / Parts No		Qty		
								Billing Amount				
Compressor manufacturing No.				Defective Compressor		Replacement Compressor						
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code						
	Yes / No	Yes / No	Yes / No	Yes / No								
Service Engineer Remarks												
Name: <u>Firoz</u> Signature: <u>[Signature]</u>												
Customer Remarks												
Name: <u>[Signature]</u> Signature: <u>[Signature]</u>												
Customer Impression about Service												
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)												
How is the behavior of visited engineer												
What is the level of your satisfaction												
How is the explanation by Engineer												
a Simple Repair												
b Part Replaced												
c Part Repaired												
d Gas Charging done												
e Routine Service - Wet												
f Routine Service - DRY												
Fault Diagnosed												
Power Failure												
Phase Reverse												
In door unit PCB Defective												
Out door PCB Defective												
In door unit Fan Motor Defective												
Outdoor Fan Motor Defective												
Comp. taking High Current / Amp												
Compressor Ground / Earth												
Compressor tripping due to High Temperature												
Compressor tripping due to High Pressure												
Indoor Unit MgsW Defective												
Outdoor Unit MgsW Defective												
Indoor Unit Transformer Faulty												
Outdoor Unit Transformer Faulty												
Fault of swing Motor												
Defect of Drain Pump												
Expansion Valve Body / Motor Defective												
Defective Temperature Sensor of Indoor Unit												
Defective Temperature Sensor of Outdoor Unit												
Defective Current Sensor in Outdoor Unit												
Gas Leakage at Indoor Unit												
Gas Leakage at Outdoor Unit												
Blower broken												
Short Cycling of Air at Indoor Unit												
Short Cycling of Air at Outdoor Unit												
Defect in Drain piping System												
Gas Leakage from Flare nut												
Error in Transmission wiring												
Product under capacity												
Rat bite case												
Less cooling problem due to dirty Airfilter												
Remote setting changed												
Clogged Condenser												
Other - Pl. specify												
Details of Repair Work Done												
a Simple Repair												
b Part Replaced												
c Part Repaired												
d Gas Charging done												
e Routine Service - Wet												
f Routine Service - DRY												

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; es@daikinindia.com / www.daikinindia.com

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Ratu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Firoz					
User: <u>ICICI Bank</u>				Mobile:		Operation data (Ambient temp. °C)			
Customer Address: <u>Raj Nirvana Shop No: 15.16</u>						Before repair		After repair	
I Base Address: <u>Anand Greenland - Pale Road.</u>						HP / T		pslg/ pslg/	
Daikin Invoice:				Date:		SP / T °C		pslg °C pslg °C	
Dealer Invoice:				Date:		Current °C		Amps °C Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts Volts	
Outdoor unit /		<u>R1km35uvlcwA</u>		<u>3108</u>		Suction		°C °C	
Indoor unit		<u>FT1km35uvlcwA</u>		<u>3664</u>		Discharge		°C °C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work					
<u>02</u>				Installation Done					
<u>01</u>				Now A/C working					
<u>24</u>				Cooling Fitter					
Compressor manufacturing No.				Defective Compressor		Replacement Compressor			
Installed date		Warranty	AMC	Using with		Fault location	Phenomena code	Error code	
		Yes / No	Yes / No	Stabilizer Cut off					
Service Engineer Remarks				Signature		Total			
Name: <u>Firoz</u>				Signature		Code:			
Customer Remarks				Signature		Customer Impression about Service			
Name				Signature		(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)			
						How is the behavior of visited engineer			
						What is the level of your satisfaction			
						How is the explanation by Engineer			
						a Simple Repair			
						b Part Replaced			
						c Part Repaired			
						d Gas Charging done			
						e Routine Service - Wet			
						f Routine Service - DRY			
						Details of Repair Work Done			
						✓			

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

Subject: Installation

[illegible]

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Rutu Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order		
				Firoz						
User: ICICI Bank				Mobile:		Operation data (Ambient temp. °C)			Fault Diagnosed	
Customer Address: Raj Nirvana Shop No: 15, 16									✓	
Base Address: Anand Greenland, Patel Road.										
Daikin Invoice:				Date:						
Dealer Invoice:				Date:						
Type		Model No		Manufacturing No.						
Outdoor unit /		R1m3SUV16WA		3109						
Indoor unit		FT1m3SUV16WA		3684						
Work Date		No. of S.E.		Work hours		Progress code		Details of the Repair Work		
02								Installation Done		
01								Now A/C working		
25								Cooling Fine.		
Compressor manufacturing No.		Defective Compressor		Replacement Compressor						
Installed date		Warranty		AMC		Using with		Fault location		
		Yes / No		Yes / No		Stabilizer Cut off		Phenomena code		
								Error code		
Service Engineer Remarks										
Name: Firoz										
Signature										
Customer Remarks										
Name										
Signature										
Customer Impression about Service										
(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)										
How is the behavior of visited engineer										
What is the level of your satisfaction										
How is the explanation by Engineer										
a Simple Repair										
b Part Replaced										
c Part Repaired										
d Gas Charging done										
e Routine Service - Wet										
f Routine Service - DRY										

DAIKIN AIRCONDITIONING INDIA PVT. LTD.

Service Completion Certificate



AEON AIRCONDITIONING SOLUTIONS

Office No. 108 & 109, Devashree Garden, Commercial Complex,
R.W. Swaant Marg, above Sheetal Dairy, Rube Park, Thane - 400 601.
Mob.: 9322334107 / 9322334109

393

Subject: Installation

Registration No.		Request Date		Service Engineer		Scheduled Date/Time		Service Order	
				Firoz					
User: ICICI Bank's				Mobile:		Operation data (Ambient temp. °C)		Fault Diagnosed	
Customer Address: Raj Nirvana Shop No: 15, 16						Before repair		After repair	
Base Address: Anand Greenland Pale Road.						HP / T		psig/ psig/	
Daikin Invoice:				Date:		SP / T °C		psig/°C psig/°C	
Dealer Invoice:				Date:		Current °C		Amps °C Amps °C	
Type		Model No		Manufacturing No.		Voltage		Volts Volts	
Outdoor unit /		R13M35UV16WA		3111		Indoor temperature			
Indoor unit		FT13M35UV16WA		366S		Suction		°C °C	
Work Date	No. of S.E.	Work hours	Progress code	Details of the Repair Work		Discharge		°C °C	
02				Installation done		Outdoor temperature			
01				now A/C working		Suction		°C °C	
29				Cooling Fine		Discharge		°C °C	
Compressor manufacturing No.		Defective Compressor		Replacement Compressor		Work No / Parts No		Qty Billing Amount	
						/		/	
Installed date	Warranty	AMC	Using with	Fault location	Phenomena code	Error code			
	Yes / No	Yes / No	Stabilizer Cut off	Yes / No	Yes / No				
Service Engineer Remarks						Total			
Name: Firoz						C.A.R.			
Signature: [Signature]									
Customer Remarks						Customer Impression about Service		Details of Repair Work Done	
Name:						(Please rate on scale of 1 poor, 2, 3, 4 & 5 excellent)		a Simple Repair	
Signature: [Signature]						How is the behavior of visited engineer		b Part Replaced	
						What is the level of your satisfaction		c Part Repaired	
						How is the explanation by Engineer		d Gas Charging done	
								e Routine Service - Wet	
								f Routine Service - DRY	

Daikin Customer Care : Missed Call or SMS <DAIKIN> to 92101 88999 ; Toll Free Number : 1860 180 3900 / 1800 102 9300 ; cs@daikinindia.com / www.daikinindia.com